



**EN 510 SPECIFICATION FOR PROTECTIVE CLOTHING
FOR USE WHERE THERE IS A RISK OF
ENTANGLEMENT WITH MOWING PARTS
TEST METHODS AND REQUIREMENTS**

Check of the design	EN 510 part 3.1
Check of the ergonomic features	EN ISO 13688
Check of size designation	EN ISO 13688
Pretreatment: Washing and drying	EN ISO 15797 (industrial) or EN ISO 6330 (domestic)
Dimensional change due to cleaning	ISO 5077 after 5 cycles